



CRR Firmware Changelog

Version 1.0.7.0

Question and Technical Support Email
crr-support@atcorp.com

December 15, 2020

Contents

1. Bug fixes.....	2
2. Features/Improvements.....	2

1. Bug fixes

- Fix reported user when doing setting filter policy
- Fix caps and wording of a few help commands
- Fix ssh known host fingerprint error
- fix reported user when doing setting filter policy

2. Features/Improvements

- Added software clock service called “fake-hwclock”. This service is useful if the hardware clock is not reliable due to lack of BIOS battery. New CLI command:
 - `service fake-hwclock [disable enable restart start status stop]`
- Improved CBIT error reporting
- Improve router service shutdown/restart
- VLAN range validation
- ssh customization via new CLI commands:
 - `configure ssh server`
 - `configure ssh client`